

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number	
		TXD991304155	1	(281) 230-5747	002159631 JJK	
5. Generator's Name and Mailing Address			Generator's Site Address (if different than mailing address)			
VAM-PTS 19210 Hardy Rd. Houston, TX 77073 Generator's Phone: (281) 230-5747			VAM-PTS 19210 Hardy Rd Houston, TX 77073 (281) 230-5747			
6. Transporter 1 Company Name			U.S. EPA ID Number			
CES Environmental Services, Inc.			TXD008950461			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address			U.S. EPA ID Number			
CES Environmental Services, Inc. 4904 Griggs Rd. Houston TX, 77021 Facility's Phone: (713) 676-1460			TXD008950461			
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
		No.	Type			
	1. Non-RCRA/Non-DOT Regulated Material (Sludge)	1	TT	2,000	G	00046961
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information						
Folder ID : VAM-PTS (Hardy Road) CES Profile # CES Job # - 51555 DAF Sludge						
11a) 1338 11b) 11c) 11d)						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name			Signature		Month	Day Year
Richard Garbey			Richard Garbey		10	23 07
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name			Signature		Month	Day Year
Andres Soto			Andres Soto		10	23 07
Transporter 2 Printed/Typed Name			Signature		Month	Day Year
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
Manifest Reference Number:						
18b. Alternate Facility (or Generator) U.S. EPA ID Number						
Facility's Phone:						
18c. Signature of Alternate Facility (or Generator) Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H141		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name			Signature		Month	Day Year
SAM BROWN			SAM BROWN		10	23 07